LDS-Dactron RT Pro Version 6.33

May 12, 2008

Changes

TestTrack	Description
	Resolves tachometer triggering issue with the new PHOTON+ hardware. Release version of RT Pro for PHOTON+