## **LDS-Dactron RT Pro Version 6.21**

January 16, 2007

## **Bug Fixes**

New Internet Explorer 7.0 causes a script error to appear on the Start-up page when the RT Pro software is started.