



# Product Release

## **Dactron RT Pro Version 6.34.9104 ActiveX API 1.92**

**April 20, 2009**

The changes in 6.34.9104 are only to the ActiveX API software. There are no changes to the RT Pro applications.

### **Enhancements**

- 9062 RT Pro ActiveX API - User requires frame counter status variable to determine if a block has been missed due to slow PC processing
- 9064 RT Pro ActiveX API - Allow Photon USB device to close out and reconnect without having to shut down the master program

### **Bug Fixes**

- | <i>TestTrack</i> | <i>Description</i>   |
|------------------|--|
| 9063             | RT Pro ActiveX API - Allow change of input channel voltage range without message prompt required               |
| 6866             | ActiveX API - Failed to Create RunLog File! error repeatedly encountered whenever sending ActiveX API commands |
| 6843             | ActiveX API 1.91 - Error relating to software passcode won't allow software to run                             |
| 9321             | ActiveX API - for Windows Vista the API can only be installed from the Admin account                           |