



Product Release

LDS-Dactron Shaker Control Version 6.112

December 28, 2006

Bug Fixes

2747 New Internet Explorer 7.0 causes a script error to appear on the Start-up page when the Shaker Control software is started.