

Brüel & Kjær RT Pro Version 7.41

This is a maintenance release and includes the following bug fix:

Windows® 10 updates have caused issues with the Windows® application and the search button that, for some installations, stops working when RT Pro 7.4 is installed. A fix has been identified and is included in the 7.41 release.